5210000 Concrete Barriers, Traffic Railing, Barriers and Parapets
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

JC Miseroy
(813) 367-9635
jc.miseroy@gcinc.com

Comments: (Industry, 12-4-17)
The language about not having to repair cracks in unreinforced, plain concrete barrier (unless directed by the Engineer) has been deleted. What are the plans for handling of these cracks?
Response: Per the FY 2018-19 Standard Plans, Index 521-001(Concrete Barrier), all Concrete Barrier is now fully reinforced. Per Specifications Section 521-7, "The disposition of concrete cracks in ~~barrier wall~~rigid barrier after installation shall be in accordance with 400-21." ~~Cracks in unreinforced, plain concrete barrier wallrs as detailed in Design Standards, Index No. 410 do not require repair unless directed by the Engineer.~~

****