FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2017 - 2022, EXTRACTED ON 11/30/2016

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = GILCHRIST ----------

RDWYID / SR / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / US / W_BMP / W_BMP / W_BMP	EMP / G_BMP / G_EMP / W_EMP / W_EMP	RW / LN / RW / RW / RW	SYS / %T / SURFTYPE / FY-P / ASTYPE / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS RATINGS / SURVEYED YEAR	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	FUTURE 2021 (FAST)
31010000	0.000	0.198	C	1	1	45	CRACKING	10.0		10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.0	6.5	6.5	6.0*		
26			2	4.5	5200		RIDE	8.2		8.7	7.8	8.8	8.5	8.2	8.3	8.4	8.4	8.2	8.2	7.5		
FANNING SPRINGS CITY LIM(0.0C)					FC125																	
							CRACKING	3.5*	3.5*	9.0	8.5	8.5	8.5	8.0	7.0	7.0	7.0	6.0*	6.0*	6.0*		
				(2006)			RIDE	7.0	6.8	6.8	7.0	7.3	7.7	5.8	7.6	7.6	7.3	7.4	7.1	6.9		
31010000	0.198	7.523	C	1	1	60	CRACKING	10.0		10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.0	6.5	6.5	6.0*		
26			2	4.5	6300		RIDE	8.4		8.7	7.8	8.8	8.5	8.2	8.3	8.4	8.4	8.2	8.2	7.5		
SIDE ROAD(0.3C)					FC95																	
2097872	0.150	4.364	C	2005	0012		CRACKING	3.5*	3.5*	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5	7.0	7.0	7.0	5.5	
ANDERSON COLUMBIA CO., INC(2006)							RIDE	7.0	6.8	8.5	8.6	8.5	8.4	8.2	8.2	8.2	8.1	8.1	8.0	7.9	7.7	
31010000	7.523	17.772	C	1	1	60	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.0	7.0	5.5*		
26			2	4.5	8700		RIDE	8.4	7.8	8.2	7.7	8.4	8.2	8.1	8.2	8.3	8.3	8.1	7.9	7.4		
SW THIRD ST(7.6R)					FC125																	
2097372	10.511	15.482	C	2007	0012		CRACKING	3.5*	3.0*	1.0*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	
ANDERSON COLUMBIA CO., INC(2008)							RIDE	6.9	6.8	7.2	6.3*	8.4	8.3	8.2	8.2	8.2	8.0	8.0	7.8	7.8	7.5	
31030000	0.000	1.959	C	1	1	60	CRACKING	9.0	9.5	9.5	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	10.0	10.0		
49 129			2	8.3	4500		RIDE	8.6	8.2	8.9	8.0	8.8	8.3	8.5	8.7	7.9	8.2	7.9	8.8	8.7		
SW 103 ST(0.2R)					FC3																	
2097861	0.000	12.745	C	2000	0221		CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5	7.5	7.0	10.0	
WHITE CONSTRUCTION CO INC (2002)					S		RIDE	8.4	8.4	8.5	8.6	8.5	8.5	8.4	8.4	8.3	8.3	8.2	7.9	8.1	8.1	
4376201	0.000	2.767	C	2019	0012																	
31030000	1.959	2.778	C	1	1	30	CRACKING	7.0	5.5*	5.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0		
49 129			2	12.2	6500		RIDE	7.6	8.1	8.0	7.9	8.2		8.8	8.6	8.5	8.5	8.4	8.5	8.3		
SE SECOND AVE(2.0R)					FC3																	
2097771	1.944	2.733	C	1996	0224		CRACKING	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	6.0*	6.0*	5.5*	10.0	
V E WHITEHURST & SONS INC (1997)					S		RIDE	8.0	8.0	7.9	7.9	7.6	7.2	7.3	7.1	7.3	7.1	7.1	6.8	7.2	8.1	
4376201	0.000	2.767	C	2019	0012																	
31030000	2.778	12.804	C	1	1	60	CRACKING	8.5	7.0	7.0	6.0*	6.0*	5.5*	3.5*	3.5*	3.5*	3.5*		10.0	10.0		
49 129			2	12.2	4500		RIDE	8.3	8.5	8.4	7.9	8.0	7.4	7.4	7.4	7.2	6.8		8.9	8.8		
SW 17 CT(4.7L)					FC3																	
2097861	0.000	12.745	C	2000	0221		CRACKING	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.5	7.0	7.0	6.0*		
WHITE CONSTRUCTION CO INC (2002)					S		RIDE	8.6	8.6	8.5	8.5	8.3	8.3	8.2	8.2	8.1	7.9	7.9	7.8	7.8		
4391161	2.767	12.804	C	2020	0012																	
31030000	12.804	23.488	C	1	1	60	CRACKING	7.0	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	7.5	7.5	4.5*		
49 129			2	12.2	4900		RIDE	7.0	7.3	7.2	7.2	7.0	8.3	8.2	8.1	8.8	8.7	8.6	8.5	8.1		
RODEO RD(12.9L)					FC125M																	
2097692	12.804	23.488	C	2007	0012		CRACKING	4.5*	3.5*	1.0*	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	6.0	
ANDERSON COLUMBIA CO., INC(2009)							SPRIDE	7.1	6.9	6.5	6.4*	6.1*	8.6	8.4	8.3	8.3	8.1	8.0	7.9	7.9	7.7	
31040000	0.000	0.612	R	1	1	35	CRACKING	10.0	10.0	10.0	7.0	7.0	6.5	4.5*	4.5*	3.5*		10.0	10.0	10.0		
55 19			2	16.9	10900		RIDE	8.3	8.5	8.5	8.1	8.5	7.8	8.2	8.1	7.6		8.2	8.2	8.0		
SIDE ROAD(0.0C)					FC125																	
2097841	0.000	0.612	C	2000	0012		CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	6.0*	6.0*	6.0*		
ANDERSON COLUMBIA CO INC (2001)							SPRIDE	8.0	7.9	7.9	8.0	7.9	7.9	7.8	7.8	7.7	7.6	7.5	7.3	7.3		
31040000	0.000	0.612	L	1	1	35	CRACKING	10.0	10.0	10.0	7.0	7.0	6.5	4.5*	4.5*	3.5*		10.0	10.0	10.0		
55 19			2	16.9	10900		RIDE	8.5	7.7	8.7	8.3	8.5	8.3	7.9	7.8	7.7		8.3	8.2	8.0		
SIDE ROAD(0.0C)					FC125																	
2097841	0.000	0.612	C	2000	0012		CRACKING	10.0	10.0	10.0	9.0	9.0	8.5	8.0	7.0	7.0	7.0	6.0*	6.0*	6.0*		
ANDERSON COLUMBIA CO INC (2001)							SPRIDE	7.9	7.8	7.9	7.9	7.9	7.9	7.8	7.8	7.7	7.6	7.5	7.1	7.2		
31050000	0.000	8.813	C	1	1	60	CRACKING	9.0	8.5	8.5	7.5	7.0	7.0	5.5*	3.5*	3.5*	3.0*	3.0*	10.0	10.0		
47			2	14.2	2400		RIDE	8.6	8.8	8.8	8.8	8.8	8.5	8.8	8.7	7.8	7.9	7.6	8.7	8.4		
SR 49(0.0C)					FC125																	
2097891	0.000	8.792	C	2001	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	5.5	
V E WHITEHURST & SONS INC (2002)							SPRIDE	8.4	8.3	8.3	8.4	8.3	8.3	8.3	8.3	8.3	8.2	8.1	8.0	7.8	7.5	
31050000	8.813	18.364	C	1	1	60	CRACKING	7.0	6.5	10.0	8.5	8.5	7.0	5.5*	3.0*	3.0*	3.0*	3.0*	3.0*	10.0		
47			2	14.2	1800		RIDE	7.7	7.7	8.9	8.9	8.8	8.4	8.4	8.2	8.4	8.4	8.2	8.1	8.6		
SE 5 TRL(9.1L)					FC125																	
2097722	8.792	18.303	C	2002	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.0	6.5	
ANDERSON COLUMBIA CO., INC(2003)							SPRIDE	8.4	8.4	8.3	8.5	8.4	8.4	8.3	8.3	8.3	8.2	8.2	8.1	7.9	7.6	

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2021 FORECASTED BY FLORIDA'S ANALYSIS SYSTEM FOR TARGETS(FAST).