



| ALT | ITEM NO.   | DESCRIPTION                                  | UNITS | FA/NFA<br>QUANTITY |
|-----|------------|--|-------|--------------------|
|     | 0520 2 9   | CONCRETE CURB, SPECIAL                       | LF    | 50.000             |
|     | 0520 3     | VALLEY GUTTER- CONCRETE                      | LF    | 30.000             |
|     | 0520 6     | SHOULDER GUTTER- CONCRETE                    | LF    | 10.000             |
|     | 0522 1     | SIDEWALK CONCRETE, 4" THICK                  | SY    | 80.000             |
|     | 0522 2     | SIDEWALK CONCRETE, 6" THICK                  | SY    | 80.000             |
|     | E101 1 1   | MOBILIZATION                                 | LO    | 10.000             |
|     | E102 74 9  | TRAFFIC CONES                                | ED    | 200.000            |
|     | E102100 16 | NECESSARY MAINT SERVICE (ROUND TRIP EXPENSE) | EA    | 10.000             |
|     | E460 82    | BOLT TIGHTENING                              | EA    | 100.000            |
|     | E521 1     | CONCRETE BARRIER WALL REPAIR                 | CY    | 8.000              |
|     | E524 1 1   | CONCRETE DITCH PAVEMENT REPAIR               | CY    | 5.000              |
|     | E560 1     | PAINT STRUCTURAL STEEL                       | SF    | 200.000            |
|     | E561 1     | PAINT STRUCTURAL STEEL (INORGANIC ZINC)      | SF    | 75.000             |
|     | E562 1     | PAINT STRUCTURAL STEEL (ZINC)                | SF    | 75.000             |
|     | E700 96 1  | SIGN SUPPORT REPAIRS (ALUMINUM)              | LB    | 75.000             |
|     | E700 96 2  | SIGN SUPPORT REPAIRS (STEEL)                 | LB    | 100.000            |