



| ALT | ITEM NO.   | D E S C R I P T I O N                                | UNITS | FA/NFA<br>QUANTITY |
|-----|------------|------------------------------------------------------|-------|--------------------|
|     | 0339 1     | MISCELLANEOUS ASPHALT PAVEMENT                       | TN    | 15.000             |
|     | 0400 1 25  | CONC CLASS I, MASS SUBSTRUCTURE                      | CY    | 5.000              |
|     | 0400 2 4   | CONC CLASS II, SUPERSTRUCTURE                        | CY    | 5.000              |
|     | 0400 3 20  | CONC CLASS III, SEAL                                 | CY    | 5.000              |
|     | 0400 4 4   | CONCRETE CLASS IV, SUPERSTRUCTURE                    | CY    | 3.000              |
|     | 0400145    | CLEANING CONCRETE SURFACE                            | SF    | 20,000.000         |
|     | 0401 70 1  | RESTORE SPALLED AREAS, EPOXY                         | CF    | 50.000             |
|     | 0411 1     | EPOXY MATERIAL FOR CRACK INJECTION- STRUCTURES REHAB | GA    | 10.000             |
|     | 0411 2     | CRACKS INJECT & SEAL- STRUCTURES REHAB               | LF    | 450.000            |
|     | 0415 1 6   | REINFORCING STEEL- MISCELLANEOUS                     | LB    | 250.000            |
|     | 0514 71 1  | PLASTIC FILTER FABRIC, SUBSURFACE                    | SY    | 150.000            |
|     | 0515 1 2   | PIPE HANDRAIL - GUIDERAIL, ALUMINUM                  | LF    | 20.000             |
|     | 0515 3 1   | PIPE HANDRAIL, STEEL                                 | LF    | 35.000             |
|     | 0520 2 9   | CONCRETE CURB, SPECIAL- BRIDGE TRANSITION BLOCK      | LF    | 25.000             |
|     | 0521 1     | MEDIAN CONCRETE BARRIER WALL                         | LF    | 25.000             |
|     | 0524 2 2   | CONCRETE SLOPE PAVEMENT, NON REINFORCED, 4"          | SY    | 20.000             |
|     | 0530 1     | RIPRAP, SAND-CEMENT                                  | CY    | 30.000             |
|     | 0530 3 3   | RIPRAP- RUBBLE, BANK AND SHORE                       | TN    | 25.000             |
|     | E101 1 1   | MOBILIZATION                                         | LO    | 50.000             |
|     | E102 20    | PORTABLE LIGHTING UNIT (MAST MOUNTED)                | ED    | 45.000             |
|     | E102100 16 | NECESSARY MAINT SERVICE (ROUND TRIP EXPENSE)         | EA    | 3.000              |
|     | E350 74 6  | PAVEMENT JOINT (HOT POURED > 3/4")                   | LF    | 3,000.000          |
|     | E460 20 1  | POLYMER JOINT REPLACEMENT                            | CF    | 30.000             |
|     | E460 20 2  | POLYMER CONCRETE HEADER REPAIR                       | CF    | 50.000             |
|     | E460 20 14 | ELASTOMERIC STRUCT JOINT SEAL REPLACE                | LF    | 2,100.000          |
|     | E500 72    | HANDRAIL ALUMINUM (REMOVE & REINSTALL)               | LF    | 75.000             |
|     | E560 1     | PAINT STRUCTURAL STEEL                               | SF    | 30.000             |