

provide minimum or maximum tolerances as approximately leaves too much interpretation.

Response:

Tommy Cook
850-415-9239
tommy.cook@dot.state.fl.us

Comments:

Recommend changing section **701-4.2 Thickness:** read **701-4.2 Vibratory Line Thickness** if that is indeed what this section is referencing. I would also like to see more clarity in this section regarding the inverted profile dimensions. Evidently my interpretation of inverted profile is opposite of this specs definition.

Recommend in section **701-4.3 Dimensions of Transverse Audible Bars:** the first sentence to remove “vibratory” as the previous section should be labeled to address Vibratory lines. This title references Audible Bars. Questions have been raised as to the need for a drainage channel in each of the bars. There is no specification in this section that limits the height of the bars. Lastly, we would recommend changing the word “approximately” to a range to discourage potential disagreements.

Response:
