

6340203 Span Wire Assembly
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

D4

Comment: (5-15-14) Dist. 4 Const has no comments on the proposed spec. change but as an aside, please consider the following: Std Index 17727: In all types of conc. strain poles the index call for 3/4" diameter holes for span wire bolts. The spec. requires bolts larger than 3/4" depending on the diameter/number of span wires. Suggest you change the standard from 3/4" to "varies, refer to standard specifications".

Response: Agree, Will make the revision to the Index. Thanks for your comment.
