

6490000-2 GALVANIZED STEEL STRAIN POLES, MAST ARMS, AND MONOTUBE  
ASSEMBLIES  
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

---

Dan Hurtado  
414-4155  
[dan.hurtado@dot.state.fl.us](mailto:dan.hurtado@dot.state.fl.us)

Comment: (6-12-14)

1. The version posted for online review does not incorporate previous changes made by Andre Pavlov for the addition of structural grout pads and clarification of bolt tightening.

Response: From the Specs Office - The changes proposed by Andre are being processed separately as revision 6490000 (this one is 6490000-2). This is not an ideal situation and we apologize for any confusion. The Specs Office will consolidate all the approved changes into one document for publishing the 2015 eBook.

2. 649-5, second sentence. "mast arms" should be left as "mast arm poles". Since the mast-arm is the the horizontal member of the structure, eliminating the word "pole" allows the contractor to erect the upright member of the assembly prior to the required concrete strength gain.

Response: Agree. Change made.

\*\*\*\*\*

Don Conner  
813-759-1559  
[djc@highwaysafetydevices.com](mailto:djc@highwaysafetydevices.com)

Comment: (6-20-14)

Does Section 975-4 require revision to specifically call out CCTV poles since they are now being referenced in 649-2.1?

Response: We will consider this for possible future revisions to Section 975. However, no change is necessary to 975-4 at this time. Article 649-2.1 requires all pole assemblies (including CCTV poles) to use coating products meeting the requirements of Section 975.  
No change made.

\*\*\*\*\*