

5210403 CONCRETE BARRIERS, TRAFFIC RAILING B ARRIERS AND PARAPETS
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

D4 Construction

Comments: (10-31-12)

D4 Const. has the following comments: "cover tolerance is plus or minus 1-1/4 inches" This tolerance does not seem to be workable. If required cover is 2", we would fall back to the 1-3/4" minimum mentioned later. Are there cases we could live with this large of a tolerance?

Response:
