



Florida Department of Transportation

RICK SCOTT
GOVERNOR

605 Suwannee Street
Tallahassee, FL 32399-0450

ANANTH PRASAD, P.E.
SECRETARY

January 14, 2013

Monica Gourdine
Program Operations Engineer
Federal Highway Administration
545 John Knox Road, Suite 200
Tallahassee, Florida 32303

Re: Office of Design, Specifications
Section **556**
Proposed Specification: **5560700 JACK AND BORE.**

Dear Ms. Gourdine:

We are submitting, for your approval, two copies of the above referenced Supplemental Specification.

These changes were proposed by Gordon Wheeler, of the State Roadway Design Office, to delete pay items from the Jack & Bore specification and include with Section 630 for conduit, and Section 430 for pipe.

Please review and transmit your comments, if any, within two weeks. Comments should be sent via email to SP965TT or trey.tillander@dot.state.fl.us.

If you have any questions relating to this specification change, please call me at 414-4140.

Sincerely,

V. Y. "Trey" Tillander, III, P.E.
State Specifications Engineer

TT/cah

Attachment

cc: Florida Transportation Builders' Assoc.
State Construction Engineer

JACK AND BORE.(REV ~~11-2712-147-132~~)

ARTICLE 556-7 (Page 737) is deleted and the following substituted:

556-7 Method of Measurement *Compensation*.

~~The method of measurement will be the actual length of the installation, measured in place along the surface of the ground, complete and accepted. No additions or deductions will be made for sweeps in either the vertical or horizontal direction to complete the installation.~~ *No direct payment will be made under this Section. Include the cost to perform this operation in the Contract unit price for the item being installed.*

No compensation will be made for failed bore paths, injection of excavatable flowable fill, products taken out of service or incomplete installations.

No compensation will be made for the pay item associated with the jack and bore until a Bore Path Report has been delivered to the Engineer.

ARTICLE 556-8 (Pages 737 – 738) is deleted.

556-8 Basis of Payment.

~~556-8.1 General: Price and payment will be full compensation for all work and materials required to complete the work specified in this Section, including furnishing and installing casings or carrier, from plan point of beginning to plan point of ending at plan depth, removal of excavated materials and spoils, removal and disposal of drilling fluids, backfilling, and complete restoration of the site.~~

~~The installation of tracking conductors (wire or tape) will be included in the cost of the bore and will not be paid for separately.~~

~~No payment will be made for failed bore paths, injection of excavatable flowable fill, products taken out of service or incomplete installations.~~

~~No payment will be made for jack and bore until a Bore Path Report has been delivered to the Engineer.~~ *556-8.2 Jack & Bore used as a Casing: When the installed product is used as a casing, the casing is included in the cost of the bore. Internal pipe or other contents will be paid separately under the applicable Section for the contents.*

556-8.3 Jack & Bore used as a Carrier without a Casing: When the installed product is used as carrier without a casing for liquids or gases, the carrier is included in the cost of the bore. No separate payment will be made for the work or materials under other Sections for the bore length.

~~Payment will be made under:~~

~~Item No. 556-1 Jack and Bore per foot of bore diameter.~~

JACK AND BORE.

(REV 1-14-13)

ARTICLE 556-7 (Page 737) is deleted and the following substituted:

556-7 Compensation.

No direct payment will be made under this Section. Include the cost to perform this operation in the Contract unit price for the item being installed.

No compensation will be made for failed bore paths, injection of excavatable flowable fill, products taken out of service or incomplete installations.

No compensation will be made for the pay item associated with the jack and bore until a Bore Path Report has been delivered to the Engineer.

ARTICLE 556-8 (Pages 737 – 738) is deleted.