

## FDM 261 Errata

Errata Date	Summary of Revisions
11/2/2017	Added bullet for Indexes 700-040 & 700-041, Cantilever & Span Sign Structure Truss Depth: 9.5 feet in 261.1.