

Jun 22, 11

Responses to Contractors' Questions

District: 6

Contract: T6233

Letting Date: Jun 22, 11

Letting Location: State

425478-1-52-01: SR 93/I-75 EASTBOUND ADD AUXILIARY LANE(S)

Question # 1

Q: Landscape plans show tree relocation and give locations for the relocated trees/palms. Relocation note #3 on sheet LD-4 states that relocated material can be moved to a location within 10 miles of limits of construction. Does the Department plan on moving any trees/palms off site or are the proposed locations as shown on the plans firm?

A: All trees will be relocated within the project limits as shown on the Landscaping Plans.

Question # 2

Q: Pay Item 700-23-112 Overhead Truss Cantilever Sign:
The tabulation of quantities shows 2 EA. The plans show one structure at STA 474+00 on sheet S-12, S-37, and S-41. The other structure is not shown in the plan sheets, cross sections, or the structure data table. Is the actual quantity 1 EA for Pay Item 700-23-112? If not, please provide the information on the second structure.

A: Pay Item 700-23-112 incorrectly has quantities 2 EA. Only one sign structure is required on this project, and the quantities will be underun.