




[contact us](#) | [what's new](#) | [FAQ's](#) | [links](#)



District One Construction

Proposal Number: T1428
Financial Project Number: 425232-1-52-01

Question	Response
<p>The summary of quantity sheet number 6 has a listing of manholes to be adjusted and inlets to be adjusted. Will the manholes be jack hammered out and put back with new hardware? The manholes look to be flush with existing road way. What adjustments are to be done at the inlets? There are water valves within 3 or 4 feet of the manholes are these to be adjusted also? On sheet # 5 there is a listing of detectable warnings for curb ramps. After a site visit we saw that when the contractor installs the detectable surface they will not be in compliance with the 2010 standard ADA. Will any sidewalk need to be replaced in these locations that is not stated on the drawings?</p>	<p>Answers Posted on 3/23/2011 @ 7:47AM: Question 1. The summary of quantity sheet number 6 has a listing of manholes to be adjusted and inlets to be adjusted. Will the manholes be jack hammered out and put back with new hardware? The manholes look to be flush with existing road way. What adjustments are to be done at the inlets? Answer 1. The listing of manholes and inlets to be adjusted on sheet number 6 are only for the storm drains. The Contractor is responsible that all manholes and inlets listed on sheet number 6 be flush with final grade of the roadway. Question 2. There are water valves within 3 or 4 feet of the manholes are these to be adjusted also? Answer 2. These valves were identified in the plan sheets and shall be adjusted by the utility company. There is a utility work schedule to accommodate time for this work. Question 3. On sheet # 5 there is a listing of detectable warnings for curb ramps. After a site visit we saw that when the contractor installs the detectable surface they will not be in compliance with the 2010 standard ADA. Will any sidewalk need to be replaced in these locations that is not stated on the drawings? Answer 4. The summary box is identifying the existing ramps that only need detectable warnings and no sidewalk is to be replaced. These existing ramps are ADA compliant based on field reviews for existing ramp criteria.</p>

[Return to Bid Questions](#)

[Print Page](#)

This site is maintained and published by the Florida Department of Transportation's