

**Bid Questions and Answers Report**

Date &amp; Time:

6/19/2013 3:26:59 PM

District Address: District 5 Construction Office, located at 719 South Woodland Blvd, Deland, FL 32720

District Phone: (386) 943-5350

Proposal: T5470

Project: 430672-1-52-01

Letting Date: 6/19/2013

Location: CENTRAL OFFICE

Description: SR 423, SR 438, AND SR 500

---

Question: 4199: Can the comp book for this project be made available? Posted: 6/4/2013 8:53:04 AM

---

Answer: The Department does not guarantee the details or computations contained within the computation book. The computation book is provided for informational purposes only and is not part of the contract documents. The bidder shall make independent calculations and base the bid solely on these calculations. The bidder's submission of a proposal is prima facie evidence that the bidder has not relied on the computation book. No claim for compensation may be based on an inaccuracy contained within the computation book. The computation book is available for download from you order history in online ordering. URL: <https://www3dot.state.fl.us/ContractProposalProcessingOnlineOrdering/>

Status: ANSWER PUBLISHED  
Posted: 6/10/2013 4:26:13 PM

---

Question: 4254: Plan sheet 66 has a detail for alternate B-1 and C for sidewalk construction. The areas of sidewalk to which these alternates pertain to can't be quantified based on the information in the plans. Can the department provide information that would help quantify the sections of sidewalk being constructed per alternate B-1 or C?

Posted: 6/6/2013 2:44:52 PM

---

Answer: The Alternate B-1 and Alternate C details on sheet no. 66 state that the "Thickened Portion of Concrete Sidewalk to be Included in Cost of Sidewalk" and "Raised Portion of Concrete Sidewalk to be included in the Cost of Sidewalk". The limits of these details are shown in the plan/profile and cross section sheets.

Status: ANSWER PUBLISHED  
Posted: 6/10/2013 7:57:01 AM

---

Question: 4260: plan sheets reference index 862 for the 42" aluminum handrail on the project. There is no index 862 in the 2010 Design Standards, and the 862 index is not accessible on the departments website in pdf format. Is this project using the 2013 Design Standards? If so, can the department provide the details for index 862?

Posted: 6/6/2013 4:46:21 PM

---

Answer: The plans (Keysheet) reference the 2013 standards and the website that was referenced in the plans (Keysheet) is working you will be able to download the index in PDF format.

Status: ANSWER PUBLISHED  
Posted: 6/10/2013 8:08:49 AM

<http://www.dot.state.fl.us/rddesign/DesignStandards/Standards.shtm>

---

Question: 4264: Are detectable warning surfaces required at only the handicap ramps leading to the crosswalks? If there are other requirements that determine the location of the detectable warning surfaces, please specify. Posted: 6/6/2013 5:18:44 PM

---

Answer: Placement of detectable warning surfaces is defined in the FDOT Design Standards with particular attention to Index 304 and Index 310 Status: ANSWER PUBLISHED  
Posted: 6/10/2013 7:54:49 AM