



Bid Questions and Answers Report

Date & Time:

3/27/2013 1:56:24 PM

District Address: District 2 Construction Office, located at 1109 South Marion Avenue, Lake City, FL 32025

District Phone: (386) 961-7532

Proposal: T2464

Project: 210538-4-52-01

Letting Date: 3/27/2013

Localtion: CENTRAL OFFICE

Description: SR 10 (US 90)

---

Question: 2836: Plan Sheets 19 - 21 show the location of multiple "Monitoring wells". These wells appear to be in direct conflict with either new Asphalt Paving, new Concrete Sidewalk, or new Concrete curb and gutter. Can you please clarify what is to be done with the existing monitoring wells? Posted: 3/11/2013 5:42:07 PM

---

Answer: All the conflicting monitoring wells have been abandoned and will be capped by others. Status: ANSWER PUBLISHED

Posted: 3/12/2013 5:02:16 PM