



Florida Department of Transportation

RICK SCOTT
GOVERNOR

801 North Broadway Avenue
Bartow, FL 33830

ANANTH PRASAD, P.E.
SECRETARY

December 30, 2014

ADDENDUM NUMBER ONE

TO: PROSPECTIVE BIDDERS AND PLAN HOLDERS
PROPOSAL/CONTRACT ID: E1002
FINANCIAL PROJECT NO.: 431615-1-52-01
COUNTY(IES): Charlotte

LETTING DATE: JANUARY 15, 2015

DESIGN STANDARDS EBOOKLET & PLAN REVISIONS

The following Plan Revisions have been made:

Sheet No.	Rev. Date	Description
1	12/17/2014	Added list of Revised Standard Index Drawings
2A	12/17/2014	Added new Signature Sheet
1-12 of 12	12/17/2014	Added Revised Standard Index 600
3 of 3	12/17/2014	Added Revised Standard Index 11200
4 of 8	12/17/2014	Added Revised Standard Index 11860
1 of 1	12/17/2014	Added Revised Standard Index 17302
1-5 of 5	12/17/2014	Added Revised Standard Index 17347

The following revisions have been made to the Design Standards eBooklet.

Index No.	Index Name	Sheet No.	Revision
11200	Multi-Column Ground Signs	3 of 3	Deleted the SHIM Column for the Table; Changed the rotation of the Stiffener Plate
11860	Single Column Ground Signs	4 of 8	Added Note for the Diamond Signs
11862	Roadside Flashing Beacon Assembly	1 of 7	Changed the Anchor Bolt length to 18"; changed Note #5 Specification reference
		2 of 7	Changed the Anchor Bolt length to 18"
		3 of 7	Clarified Solar Battery Compartment and Beacon Controller
		4 of 7	Changed the Anchor Bolt length to 18"
		5 of 7	Changed the Anchor Bolt length to 18"; Clarified Solar Battery Compartment and Beacon Controller
		6 of 7	Changed the Anchor Bolt length to 18"; Clarified Solar Battery Compartment and Beacon Controller
		7 of 7	Changed the Anchor Bolt length to 18"; Clarified Solar Battery Compartment and Beacon Controller; Corrected the 5'-0" dimension on the Front View.
13417	Mounting Exit Number Panels to Highway Signs	1 of 1	Delete "Sheets and Plates" note from the General Notes

17302	Typical Sections for Placement of Single & Multi-Column Signs	1 of 1	Added note to CASE VIII
17727	Signal Cable & Span Wire Installation Detail	2 of 2	Editorial Change.
17841	Cabinet Installation Details	1 of 1	Changed Notes #2 and #3 for New Controller Cabinet; Changed Note #1 for the Existing Controller Cabinet



District Procurement Services Administrator