9420203 PRECAST CONCRETE PIPE GASKETS COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Karen Byram 414-4353 ren byram@dot state

karen.byram@dot.state.fl.us

Comments: (11-25-15)

A certification requirement needs to be added to Section 942-3. The products are not marked with the APL number and they are typically supplied by the precast facility, not the manufacturer. Therefore, the contractor needs to provide to the Engineer a manufacturer's certification, conforming to the requirements in Section 6, that the product meets the requirements of this specification when used.

Response: This change is not within our scope of changes. It will be considered at a later date. No change made.
