

Pavement Composition Data Sheet

Date: August 31, 2011

Milling Depth : 3.00 in.

Page: 1

| | | |
|---------------------------|--|--------------|
| F. P. N. : 429148-1-52-01 | S.R. No.: 570 | <u>Notes</u> |
| F. A. P. No. : N/A | From : SR 37 (Florida Avenue) | |
| County : Polk | To : Waring Road | |
| No. of Lanes : 2 @ 12' | Beg M.P. : 0.000 End M.P. : 2.550 | |

| Core No. | M.P. | Lane | Pavement Layers (in.) | | | | | | | Core Length (in.) | Percent Passing Sieves | | | | | | | | | | % Bitumen |
|----------|-------|------|-----------------------|------|-----|-----|-----|-----|------|-------------------|------------------------|---------|---------|-------|-------|--------|--------|--------|---------|---------|-----------|
| | | | FC4 | S | --- | --- | --- | --- | --- | | 3/4 in. | 1/2 in. | 3/8 in. | No. 4 | No. 8 | No. 16 | No. 30 | No. 50 | No. 100 | No. 200 | |
| 1 | 0.163 | L2 | 0.90 | 3.00 | --- | --- | --- | --- | 3.90 | 100.00 | 97.88 | 93.53 | 64.59 | 48.98 | 40.06 | 33.80 | 22.68 | 8.88 | 4.41 | 5.15 | |
| 2 | 0.547 | L1 | 0.70 | 2.90 | --- | --- | --- | --- | 3.60 | 100.00 | 99.35 | 94.92 | 69.42 | 52.26 | 40.90 | 33.73 | 24.58 | 10.70 | 6.56 | 6.54 | |
| 5 | 1.400 | L2 | 1.00 | 2.60 | --- | --- | --- | --- | 3.60 | 100.00 | 100.00 | 96.98 | 73.39 | 57.26 | 47.92 | 40.78 | 31.07 | 13.65 | 7.23 | 7.00 | |
| 6 | 1.867 | L1 | 0.90 | 3.00 | --- | --- | --- | --- | 3.90 | 100.00 | 98.47 | 95.28 | 75.32 | 57.76 | 45.54 | 37.73 | 28.34 | 11.60 | 6.24 | 7.09 | |
| 9 | 2.582 | L2 | 1.20 | 2.40 | --- | --- | --- | --- | 3.60 | 100.00 | 99.71 | 97.19 | 76.24 | 57.75 | 45.02 | 35.47 | 24.35 | 10.21 | 5.92 | 6.82 | |
| 10 | 0.247 | R1 | 0.80 | 3.40 | --- | --- | --- | --- | 4.20 | 100.00 | 97.12 | 92.68 | 69.23 | 52.17 | 41.83 | 34.48 | 22.25 | 8.19 | 3.81 | 6.06 | |

Please note that these roadway core test results are for informational purposes only and are not to be considered as a guarantee of the pavement composition other than at the locations identified in this summary.