



Pit Proctor Quarterly Report

Print Date: 9/30/2016
3:43:34PM

Valid from October 1, 2016 through December 31, 2016

DISTRICT: 01

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
01305	EARTHSOURCE INC.	B11	1	Shell Rock	9.5	126
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock		Roadway Testing Required
01730	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B11	1	Shell Rock		Roadway Testing Required
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell	9.1	125
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell		Roadway Testing Required
01800	ICS MATERIALS INC.	B11	1	Shell Rock		Roadway Testing Required
01805	MAGNUM MATERIALS, LLC	B11	1	Shell Rock		Roadway Testing Required
01807	BERMONT RESERVOIR - LAKE EXCAVATION	B02	1	Bank Run Shell		Roadway Testing Required
01815	HIGHLAND MATERIALS	B02	1	Bank Run Shell	10.0	123
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock	8.8	123
03616	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock		Roadway Testing Required
03811	846 MINE	B01	1	Limerock		Roadway Testing Required
05354	RIDGDILL & SONS INC.	B01	1	Limerock	10.0	127
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock		Roadway Testing Required
12008	CEMEX	B01	2	Limerock		Roadway Testing Required
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock	8.7	127
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock	8.5	129
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock		Roadway Testing Required
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock	8.7	127
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock		Roadway Testing Required
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock		Roadway Testing Required
17710	FREDERICK DERR & COMPANY	B12	1	Recycled Concrete Agg		Roadway Testing Required
17724	MASTERROCK LLC.	B12	1	Recycled Concrete Agg		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
 Data from Mines for Date Range: 6/21/2016 to 9/21/2016
 Reference: Section 200



Pit Proctor Quarterly Report

Valid from October 1, 2016 through December 31, 2016

Print Date: 9/30/2016
3:43:34PM

DISTRICT: 02

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock	12.6	117
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock	12.4	120
26098	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	12.1	118
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26782	LIMESTONE MATERIALS	B01	1	Limerock	12.1	119
33496	BLUE ROK INC.	B01	1	Limerock	12.1	118
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock	12.2	119
37112	SUWANNEE AMERICAN CEMENT	B01	1	Limerock	12.5	118
37112	SUWANNEE AMERICAN CEMENT	B01	2	Limerock		Roadway Testing Required
37622	DENALI INVESTMENTS INC.	B01	1	Limerock	13.7	114
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock	9.5	129
38627	A MINING GROUP, LLC	B01	1	Limerock	10.1	121
78697	EAST COAST AGGREGATES LLC	B11	1	Shell Rock		Roadway Testing Required
GA206	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate	6.5	143
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 6/21/2016 to 9/21/2016
Reference: Section 200



Pit Proctor Quarterly Report

Valid from October 1, 2016 through December 31, 2016

Print Date: 9/30/2016
3:43:34PM

DISTRICT: 03

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
53271	DOLOMITE INC.	B01	1	Limerock	14.0	115
53357	NORTH FLORIDA ROCK LTD.	B01	1	Limerock	14.0	115
53357	NORTH FLORIDA ROCK LTD.	B01	2	Limerock	13.8	115
53575	MARIANNA HI-CAL LLC	B01	1	Limerock		Roadway Testing Required
53575	MARIANNA HI-CAL LLC	B01	2	Limerock		Roadway Testing Required
53575	MARIANNA HI-CAL LLC	B01	3	Limerock		Roadway Testing Required
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
53706	ANDERSON COLUMBIA	B01	1	Limerock	12.0	120
61377	SIKES SAND & GRAVEL	B12	1	Recycled Concrete Agg		Roadway Testing Required
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	10.1	122
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate		Roadway Testing Required
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock	14.2	121
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock		Roadway Testing Required
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock		Roadway Testing Required
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock	13.8	117
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock	14.9	113
AL775	BROOKLYN LIMESTONE QUARRY	B01	3	Limerock	14.9	113

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 6/21/2016 to 9/21/2016
Reference: Section 200



Pit Proctor Quarterly Report

Print Date: 9/30/2016
3:43:34PM

Valid from October 1, 2016 through December 31, 2016

DISTRICT: 04

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina	8.7	129
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina	8.5	130
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock	8.0	130
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock	8.0	130
93366	STAR QUARRIES LLC	B01	1	Limerock		Roadway Testing Required
93366	STAR QUARRIES LLC	B11	1	Shell Rock		Roadway Testing Required
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock	8.0	128
93721	MAYACA MATERIALS	B11	1	Shell Rock	8.2	125
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Agg	14.7	113
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina	8.0	129
94745	PATRICK JAMES ECYCLE	B12	1	Recycled Concrete Agg		Roadway Testing Required
94789	STEWART MINING INDUSTRIES INC.	B03	1	Cemented Coquina	8.0	130

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 6/21/2016 to 9/21/2016
Reference: Section 200



Pit Proctor Quarterly Report

Valid from October 1, 2016 through December 31, 2016

Print Date: 9/30/2016
3:43:34PM

DISTRICT: 05

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock	12.2	118
18056	DIXIE LIME & STONE CO.	B01	1	Limerock	12.9	116
18058	CEMEX	B01	1	Limerock	12.2	118
18393	BEDROCK RESOURCES	B01	1	Limerock		Roadway Testing Required
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock	12.6	116
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock	11.7	119
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock		Roadway Testing Required
36818	MAGNUM MATERIALS	B01	1	Limerock	12.1	116
75780	S AND L MATERIALS INC.	B12	1	Recycled Concrete Agg		Roadway Testing Required
BA348	BAHAMAS ROCK LIMITED	B01	1	Limerock		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 6/21/2016 to 9/21/2016
Reference: Section 200



Pit Proctor Quarterly Report

Valid from October 1, 2016 through December 31, 2016

Print Date: 9/30/2016
3:43:34PM

DISTRICT: 06

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock	9.2	130
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock	9.5	131
87089	CEMEX	B01	1	Limerock	7.2	132
87090	CEMEX	B01	1	Limerock	7.4	132
87090	CEMEX	B01	2	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	1	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	4	Limerock		Roadway Testing Required
87339	WHITE ROCK QUARRIES	B01	1	Limerock	8.7	131
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock	7.5	133
87633	WHITE ROCK QUARRIES	B01	1	Limerock	8.7	129
87648	SDI QUARRY, INC.	B01	1	Limerock	7.7	132

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 6/21/2016 to 9/21/2016
Reference: Section 200



Pit Proctor Quarterly Report

Valid from October 1, 2016 through December 31, 2016

Print Date: 9/30/2016
3:43:27PM

DISTRICT: 07

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock		Roadway Testing Required
02675	CEMEX	B01	1	Limerock	8.5	131
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock		Roadway Testing Required
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Agg		Roadway Testing Required
13662	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Agg		Roadway Testing Required
13810	C-SQUARED CGC, INC	B12	1	Recycled Concrete Agg		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	1	Limerock		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock	12.3	117
14262	CENTRAL STATE AGGREGATES, LLC	B01	3	Limerock		Roadway Testing Required
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock	12.6	117
15755	SONNY GLASBRENNER	B12	1	Recycled Concrete Agg		Roadway Testing Required
15814	INDEPENDENCE RECYCLING OF FLORIDA INC	B12	1	Recycled Concrete Agg		Roadway Testing Required
16822	ANGELO'S RECYCLED MATERIALS	B12	1		12.0	118

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 6/21/2016 to 9/21/2016
Reference: Section 200