



# Pit Proctor Quarterly Report

Generated: 4/10/2018 08:10:11 AM

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
03340	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B01	1	Limerock Base	**	**
03616	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	9.6	128
05354	RIDGDILL & SONS INC.	B01	1	Limerock Base	10.0	126
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock Base	**	**
01305	EARTHSOURCE INC.	B11	1	Shell Rock Base	**	**
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock Base	**	**
01730	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B11	1	Shell Rock Base	**	**
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell Base	9.8	125
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell Base	9.5	126
12008	CEMEX	B01	2	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	10.3	125
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	10.0	125
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	**	**
17724	MASTERROCK LLC.	B12	1	Recycled Concrete Base	**	**
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**
01800	ICS MATERIALS INC.	B11	1	Shell Rock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/10/2018 08:10:11 AM

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01805	MAGNUM MATERIALS	B11	1	Shell Rock Base	**	**
01807	BERMONT RESERVOIR - LAKE EXCAVATION	B02	1	Bank Run Shell Base	**	**
01815	HIGHLAND MATERIALS	B02	1	Bank Run Shell Base	9.5	121
03811	THE 846 MINE	B01	1	Limerock Base	**	**
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**
13810	C-SQUARED CGC, INC.	B12	1	Recycled Concrete Base	**	**
16822	ANGELO'S AGGREGATE MATERIALS LAKELAND	B12	1	Recycled Concrete Base	**	**
91821	SAND HILL ROCK LLC	B03	1	Cemented Coquina Base	**	**
01495	SOUTHWEST AGGREGATES	B11	2	Shell Rock Base	**	**
01840	SILVER NIP	B02	1	Bank Run Shell Base	9.6	128
13844	WOODRUFF & SONS, INC.	B12	1	Recycled Concrete Base	11.0	112

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200  
 \*\* Roadway Testing Required  
 Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
72835	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	8.9	128
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
TM445	CEMEX	B01	1	Limerock Base	7.4	132
37112	SUWANNEE AMERICAN CEMENT	B01	1	Limerock Base	**	**
37112	SUWANNEE AMERICAN CEMENT	B01	2	Limerock Base	**	**
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	**	**
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.2	128
38627	CONRAD YELVINGTON DISTRIBUTORS A MINING	B01	1	Limerock Base	11.1	122
78697	EAST COAST AGGREGATES LLC	B11	1	Shell Rock Base	**	**
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	13.7	115
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	13.7	116
26098	WHITE HOLDING COMPANY, LLC.	B01	1	Limerock Base	12.2	118
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	13.2	118
33496	BLUE ROK INC.	B01	1	Limerock Base	10.6	122
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	11.8	120

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
53271	DOLOMITE INC.	B01	1	Limerock Base	12.4	116
53357	NORTH FLORIDA ROCK LLC.	B01	1	Limerock Base	12.9	116
53357	NORTH FLORIDA ROCK LLC.	B01	2	Limerock Base	12.7	115
53575	MARIANNA HI-CAL LLC	B01	1	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	2	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	3	Limerock Base	**	**
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock Base	**	**
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	12.9	117
61377	SIKES SAND & GRAVEL	B12	1	Recycled Concrete Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	**	**
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.4	146
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.4	146
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	14.9	117
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	14.1	118
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	12.9	119
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	14.9	114
AL775	BROOKLYN LIMESTONE QUARRY	B01	3	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
61391	WHITE HOLDING COMPANY LLC.	B01	2	Limerock Base	10.3	121
TM833	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.3	138
50845	ANDERSON COLUMBIA, INC.	B12	1	Recycled Concrete Base	**	**
TM842	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.3	138
AL756	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
53836	WHITE HOLDING COMPANY, LLC	B01	1	Limerock Base	12.0	120

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200  
 \*\* Roadway Testing Required  
 Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/10/2018 08:10:11 AM

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
93824	ALLSTAR AGGREGATES	B12	1	Recycled Concrete Base	**	**
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	8.4	130
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	8.5	130
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock Base	8.7	130
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	**	**
93366	STAR QUARRIES LLC	B01	1	Limerock Base	**	**
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	**	**
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	8.0	130
93721	MAYACA MATERIALS	B11	1	Shell Rock Base	8.9	125
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	15.7	113
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	8.2	130
94745	RECYCLING ROCKS	B12	1	Recycled Concrete Base	**	**
94789	STEWART MATERIALS LLC	B03	1	Cemented Coquina Base	8.4	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	11.8	123
36350	ALL STAR MATERIALS	B01	1	Limerock Base	12.9	120
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	**	**
18020	CEMEX	B01	1	Limerock Base	11.0	119
18020	CEMEX	B01	2	Limerock Base	**	**
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	**	**
18058	CEMEX	B01	1	Limerock Base	11.7	119
18058	CEMEX	B01	2	Limerock Base	**	**
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.7	117
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	13.0	114
75819	ON SITE RECYCLED CONCRETE AGGREGATE FOR	B12	1	Recycled Concrete Base	13.7	114
36818	MAGNUM MATERIALS	B01	1	Limerock Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
36812	ALL STAR MATERIALS	B01	1	Limerock Base	**	**
TM447	CEMEX	B01	1	Limerock Base	7.4	132
92757	BUCK HAMMOCK MINE	B02	1	Bank Run Shell Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock Base	**	**
36826	SCI MATERIALS	B01	1	Limerock Base	12.8	117

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
75780	S&L MATERIALS, INC.	B12	1	Recycled Concrete Base	12.5	117

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200  
\*\* Roadway Testing Required  
Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter





## Pit Proctor Quarterly Report

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87823	THE REDLAND COMPANY, INC.	B01	1	Limerock Base	9.4	130
90638	CHARLIE TOPPINO & SONS INC.	B01	1	Limerock Base	**	**
90765	GRADER MIKE, LLC	B01	1	Limerock Base	**	**
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	8.0	129
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	7.4	131
87089	CEMEX	B01	1	Limerock Base	7.2	132
87090	CEMEX	B01	1	Limerock Base	7.4	132
87090	CEMEX	B01	2	Limerock Base	**	**
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	8.2	129
87145	TITAN AMERICA, LLC.	B01	2	Limerock Base	**	**
87145	TITAN AMERICA, LLC.	B01	4	Limerock Base	**	**
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	8.0	130
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	7.2	132
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	7.7	131
87648	SDI AGGREGATES, INC.	B01	1	Limerock Base	7.1	133

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/10/2018 08:10:11 AM

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
14262	CENTRAL STATE AGGREGATES, LLC	B01	1	Limerock Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	12.0	115
14262	CENTRAL STATE AGGREGATES, LLC	B01	3	Limerock Base	**	**
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock Base	11.8	117
15755	SONNY GLASBRENNER	B12	1	Recycled Concrete Base	**	**
13662	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock Base	11.0	121
02675	CEMEX	B01	1	Limerock Base	7.7	133
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	12.3	116
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.7	126
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	**	**
02834	HOLCIM US	B01	1	Limerock Base	10.1	124
15814	INDEPENDENCE RECYCLING OF FLORIDA INC.	B12	1	Recycled Concrete Base	**	**
15820	ANGELO'S AGGREGATE MATERIALS ST. PETE	B12	1	Recycled Concrete Base	**	**
15838	ANGELO'S RECYCLED MATERIALS LARGO	B12	1	Recycled Concrete Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/10/2018 08:10:11 AM

**Valid from 04/01/ 2018 to 06/30/ 2018**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 99

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
BA348	BAHAMA ROCK LIMITED	B01	1	Limerock Base	**	**
GA206	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate Base	**	**
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate Base	**	**
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate Base	**	**
AL612	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.4	146
AL519	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.3	138
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2018 to 03/31/ 2018 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter